District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Revised March 17, 1999

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

1220 S. St. Flai	KIS DI., SAIII	a 1 c, 141vi 6750.	J	Sa	anta F	e, NM 875	05					Side of term
30-015-10394 Release Notification and Corrective Action												
nMLB//29140/04 OPERATOR Initial Report Final Report												
Name of Company Devon Energy 6/37						Contact Roger Hernandez						
Address P. O. Box 250						Telephone No. 575748-5238						
Artesia, NM 88211												
Facility Name Jones Federal B #3						Facility Type Oil Well						
Surface Owner Mineral C						wner			Lease No.			
				LOCA	ATIO	N OF RE	LEASE					
Unit Letter	Section	Township	Range	Feet from the		h/South Line Feet from the		East/West	Line	County		
	23	198	31E	660	South			East		Eddy County		
		<u> </u>		NAT	TIRE	OF REL	FASF	I				
Type of Rele	ase Oil				UKL		Release 32 BO	Vo	Volume Recovered 24 BO			
Source of Release						Date and Hour of Occurrence			Date and Hour of Discovery 10-1-11			
Separator Was Immediate Notice Given?									2:10 PM			
was illilledi	ate Notice		Yes [No Not R	equired	If YES, To Whom? BLM (Justin?) Carlsbad Area Office OCD (Randy Dade) Artesia Office						
By Whom? Merle Lewis						Date and Hour BLM (10-3-11 9:30 AM) OCD (10-3-11 9:35 AM)						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
IC W	-								DE	~FIV		
If a Watercourse was Impacted, Describe Fully.*						RECEIVE				ヒリ		
N/A								OCT 0.6 2011				
		em and Reme					Ise Operator shut well in and left it down until separator is repaired.					- 1
Separator we	ent off on h	igh level and o	oil was spi	aying out a vent l	ine. Le	ase Operator s	shut well in and le	eft it down u	intil sep	arator is re	paired.	,
		and Cleanup A				-1	c ,		*1			
Area impacte	a was an ar	ea approxima	tely 30'x/	0'. Area will be s	scraped	about 2" of f	surface and we wi	ill bring in n	iew soil	to remedia	ite.	
I hereby certi	fy that the i	nformation gi	ven above	is true and comp	lete to tl	ne best of my	knowledge and u	nderstand th	at purs	uant to NM	OCD r	rules and
				id/or file certain re e of a C-141 repo								
should their o	perations h	ave failed to a	dequately	investigate and re	emediate	e contamination	on that pose a thre	eat to ground	d water,	surface wa	ater, hu	ıman health
		ddition, NMO vs and/or regu		tance of a C-141	report d	oes not relieve	e the operator of r	responsibilit	y for co	mpliance v	vith an	y other
, , , , ,							OIL CONS	SERVAT	ION	DIVISIO	<u>N</u>	
a: 4	مرہ کی آما	ما مراد مواد	7		ŀ	6.1						
Signature: Adrienne Verkler						Approved by Signad Bruger Brances						
Printed Name: Adrienne Verkler						OCT 1 9 2011						
Title: Field Tech II						Approval Date: Expiration Date:						
Date: 10-4-11 Phone: (575) 748-0174										Attached		
Attach Additional Sheets If Necessary						Remediation per OCD Rules & 2RP - 92 1						201
		•		•	Guide	elines. SUB	MIT REMEDIA	TION	0	XKP	- 9	21
					PROF	OSAL NOT	LATER THAN:	•	_		-	
					Delineation required for BTEX, TPH & Chlorides							
								DIEX,	IPH 8	k <u>Chlorid</u>	<u>es</u>	