District I 1625 N. French Dr., Hobbs, NM 88240 District May and 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazo's Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

ie.

Surface Owner: ". **.**.

4. j.

 $(\hat{e}^{\dagger})^{\dagger}$

م. مار بره<u>ر دها</u>ی

Willing - Contraction alter alternation of the state

State of New Mexico Energy Minerals and Natural Resources RECEIVED

NOV- 202011-

Form C-141 vised October 10, 2003

NMQGD1 ARTIEGHAN ate District Office in accordance with 19.15.29 NMAC

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action								
nmLB1131129093	•	OPERATOR	Initial Report	Final Report				
Name of Company: Linn Operating	269324	Contact: Joe Hernandez						
Address: 2130 W. Bender Hobbs, NM 88240	กระบาร เพราะ พระเราะ	Telephone No.: 575-738-1739						
Facility Name: Skelly Unit # 199	A (12 M (m) (2 M (m)	Facility Type: Single Tank Battery	r					
Surface Owner: BLM	Mineral Owner	: BLM	API No.: 3001528	972				
n, '								

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
Ν,	15	17S	31E	1310	FSL	2546	FWL	Eddy

Latitude: 32° 49' 51.0" Longitude: -103° 51' 28.4"

NATURE OF RELEASE

Type of Release: Land PW	Volume of Release: 1	Volume Recovered: 0.5				
Source of Release: Reeduced Water	Date and Hour of Occurrence:	Date and Hour of Discovery:				
· · · · · · · · · · · · · · · · · · ·	10/28/2011 9:00am	10/28/2011 9:30am				
Was Immediate Notice Given?	If YES, To Whom?					
🗌 Yes 🛛 No 🗋 Not Required						
By Whom?	Date and Hour	······································				
Was a Watercourse Reached?	If YES, Volume Impacting the Wat	tercourse.				
🗋 Yes 🖾 No						
-If a Watercourse was Impacted, Describe Fully.*:						
and watercourse was impacted, beschot i uny.						
Describe Cause of Problem and Remedial Action Taken.*: Back pressure	valve had trash in it.					
Describe Area Affected and Cleanur Astion Takes * Disk on theid dim	and he Can be Caning					
Describe Area Affected and Cleanup Action Taken.* : Pick up fluid, disp	osed. by Gandy Service					
	· · ·					
I hereby certify that the information given above is true and complete to t	he best of my knowledge and understa	and that pursuant to NMOCD rules and				
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger						
public health or the environment. The acceptance of a C-141 report by th	e NMOCD marked as "Final Report"	does not relieve the operator of liability				
should their operations have failed to adequately investigate and remediat						
or the environment. In addition, NMOCD acceptance of a C-141 report of federal, state, or local laws and/or regulations.	loes not relieve the operator of respons	sibility for compliance with any other				
rederar, state, or local laws and/or regulations.	OU CONSERV					
	<u>OIL CONSER</u>	ATION DIVISION				
Signature:har Kapana an inter	an shi	kenne				
	Approved by District Supervisor:	SKATULSE				
Printed Name: Joe Hernandez						
	NOV 0 7 2011	•				
Title: Production Foreman	Approval Date:	Expiration Date:				
		_				
	Conditions of Approval:	•. Attached				
Date: 11-02-2011 Phone: 575-942-9492	Remediation per OCD Rules &					
Attach Additional Sheets If Necessary	delines. SUBMIT REMEDIATIO	UN PRA DUIN				
Gui	OPOSAL NOTLATER THAN:	QM741				
PRUPUSAL NOV CALL						
	12/1/2011					