


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC

### Release Notification and Corrective Action

<b>NMLB/133634980</b>		<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: Linn Operating		Contact: Joe Hernandez			
Address: 2130 W. Bender Hobbs, NM 88240		Telephone No.: 575-738-1739			
Facility Name: Max Friess # 1		Facility Type: Injection well			
Surface Owner: BLM		Mineral Owner: BLM		API No.: 3001505459	

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	30	17S	31E	660	N	1980	E	Eddy

Latitude: 32° 48' 39.1" Longitude: -103° 54' 24.6"

### NATURE OF RELEASE

Type of Release: Produced Water / Oil	Volume of Release: 2 / 8	Volume Recovered: 0.5 / 1
Source of Release: Tank	Date and Hour of Occurrence: 11/15/2011 4:54pm	Date and Hour of Discovery: 11/15/2011 5:15pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher- NM OCD / T. Gregston- BLM	
By Whom? Joe Hernandez	Date and Hour 11/16/2011 10:00am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*:

Describe Cause of Problem and Remedial Action Taken.\*: Tied 500bbl flow back to well head to flow back for acid job, well flowed at steady for 5hr and well kicked off overflowed tank oil/produced water came out top. Flow direction SW off location, N NW, on location and then off NW location. Contractor drove up to location as tank started to run over, and shut well in. Called vac truck.

Describe Area Affected and Cleanup Action Taken.\* : M & R Trucking recovered 1.5 bbl further remedial action pending.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Joe Hernandez		Signed By:	
Title: Production Foreman		Approved by District Supervisor:	
E-mail Address: jhernandez@linenergy.com		DEC 02 2011	
Date: 11/18/2011 Phone: 575-942-9492		Approval Date: Expiration Date:	
Conditions of Approval:		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules &  
Guidelines. **SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:**

1/2/2012

2RP-960