District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico **Energy Minerals and Natural Resources**

RECEIVED DEC 19 2011 NMOCD ARTESIA

Form C-141 ed October 10, 2003

2RP-983

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe NM 87505

			Rele	ase Notific		n and Co		ction				
nMLB 1135451995											Final Report	
Name of Company: Linn Operating 26 4324						Contact: Joe Hernandez						
						Telephone No.: 575-738-1739						
						Facility Type: Water Injection						
Surface Owner: BLM Mineral Owner: E												
						· · ·						
LOCATION OF RELEASE												
Unit Letter Section Township Range Feet from the No. 30 17S 31E 660					Norti	North/South Line Feet from N 66		East/West Line N	County Eddy		у	
Latitude: 32° 48' 46.5" Longitude: -103° 54' 13.7" NATURE OF RELEASE												
Type of Release: Produced Water							Release: 40	Volume Recovered: 35				
Source of Release: Pipeline -Steel							lour of Occurrence					
						12/13/2011		12/13/2011 9:30am				
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? M. Bratcher- NM OCD / Terry Gregston - BLM						
By Whom? Joe Hernandez						Date and Hour 12/13/2011 2pm						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*:												
Describe Cause of Problem and Remedial Action Taken.*: 4" trunk line, seam on pipe opened about an 1" due to corrosion. Water surfaced ran southwest												
420ft narrowest spot 1ft wide by 225ft widest point by 15ft												
Describe Area Affected and Cleanup Action Taken.*: dug up source of the leak, 12-14-11 kenemore patched line, clean up to start at later date.												
regulations all public health should their o	If operators or the environment of the environment	are required to conment. The ave failed to a ddition, NMO	report an acceptanc dequately CD accep	d/or file certain re e of a C-141 repo investigate and re	elease r rt by the emediat	otifications ar le NMOCD ma le contamination	nd perform correct arked as "Final Roon that pose a three	nderstand that purs tive actions for rele eport" does not reli eat to ground water responsibility for co	eases which eve the oper , surface wa	may en ator of ter, hu	ndanger f liability man health	
Signature: As Heaven						OIL CONSERVATION DIVISION Signed By Mile Brance Approved by District Supervisor:						
Printed Name: Joe Hernandez												
Title: Product	tion Forema	n				DEC 2 0 2011 Expiration Date:						
E-mail Address: jhernandez@linnenergy.com Date: 12/19/2011 Phone: 575-942-9492						Conditions of	Approval:	Rules &	ules &			
Date: 12/19/2011 Phone: 575-942-9492 Attach Additional Sheets If Negacogy Remediation per OCD Rules & Remediation												

Guidelines. SUBMIT REMEDIATION

PROPOSAL NOT LATER THAN: