


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

30-015-28100

Release Notification and Corrective Action

NMLA/135334597

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: LINN Energy	Contact: Joe Hernandez
Address: 2130 W Bender Blvd. - Hobbs, NM	Telephone No.: 575-942-8675
Facility Name: J.L. Keel B Tank Battery- Well #56	Facility Type: Oil and Gas Production Tank Battery
Surface Owner: BLM	Mineral Owner: BLM
Lease No.: LC-029435-B	

LOCATION OF RELEASE

Unit Letter D	Section 8	Township 17S	Range 31E	Feet from the 1280	North/South Line N	Feet from the 1300	East/West Line W	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	-----------------------	-----------------------	---------------------	----------------

Latitude: 32.853293 Longitude: -103.895982

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 48	Volume Recovered: 45
Source of Release: Corroded 4 x 3 pipe swedge	Date and Hour of Occurrence: 08/31/11 - 1600	Date and Hour of Discovery: 18/31/11 - 1630
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? T. Gregston, BLM - M. Bratcher, OCD	
By Whom?	Date and Hour: 09/01/11 - 0700	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: 4" x 3" pipe swedge corroded releasing product into the tank battery containment and previously excavated areas. Leak was isolated and the corroded swedge removed and replaced.		
Describe Area Affected and Cleanup Action Taken.*: Pending BLM conditions and additional investigation by LINN. Further detailed corrective action to be submitted.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Jose Hernandez	Signed By	
Title: Foreman	Approved by District Supervisor:	
E-mail Address: jhernandez@linneenrgy.com	DEC 19 2011	Expiration Date:
Date: Phone: 575-738-1739	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 1/19/2012

2RP-974  
(LA REENTRY)