District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 RECEIVED

DEC 13 2011

Form C-141 Revised October 10, 2003

NMOCD ART Liberary Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

MUB1135353926						OPERATOR																			
Name of Company COG OPERATING LLC 3,29/3										•															
Address 550 W. Texas, Suite 100, Midland, TX 79701						Telephone No. 432-230-0077																			
Facility Name White Oak State Tank Battery						Facility Type Tank Battery																			
Surface Owner State Mineral Own						Lease No. (API#) 30-015-29749																			
LOCATION OF RELEASE																									
Unit Letter P	Section 23	Township Range 28E Feet from the Nort.			h/South Line Feet from the East/\			West Line	est Line County Eddy																
Latitude 32.8150 Longitude 104.1392																									
NATURE OF RELEASE																									
Type of Release Produced water Source of Release Water tank										olume Recovered 5bbls tte and Hour of Discovery															
Source of Release water tank						12/01/2011 12/01/2				011 7:00 p.m.															
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required If YES, To Whom?																									
By Whom?						Date and Hour																			
Was a Watercourse Reached? ☐ Yes ☑ No						If YES, Volume Impacting the Watercourse.																			
If a Watercourse was Impacted, Describe Fully.*																									
Describe Caus	se of Proble	em and Remed	lial Action	Taken.*					<u> </u>																
The transfer p pump has been		not discharge	fluid thro	ugh new SWD lir	ne. The	e water tank fil	led up quickly an	d ran ov	er. The di	scharge line	from t	he transfer													
Describe Area Affected and Cleanup Action Taken.*																									
Initially 15bbls of produced water was released from the water tank and we were able to recover 5bbls with a vacuum truck. All free fluid remained on the location. All free fluid has been recovered and contaminated soil will be removed and hauled to disposal. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.																									
regulations all public health of should their of	operators a or the envir perations ha ment. In ac	are required to onment. The ave failed to a ddition, NMO	report and acceptance dequately CD accept	is true and compl d/or file certain re e of a C-141 repo investigate and re ance of a C-141 r	elease r rt by th emedia	notifications and le NMOCD ma te contamination	d perform correct arked as "Final Re on that pose a thre	tive acti eport" de at to gr	ons for rele oes not reli ound water	ases which eve the oper , surface wa	may en ator of ter, hui	danger liability nan health													
Signature: Printed Name: Josh Russo						OIL CONSERVATION DIVISION Signed By Mily Brance Approved by District Supervisor:																			
													Title:		HSE Co	ordinator			Approval Dat	€C 19 20	11 E	expiration I	Date.		<u> </u>
													E-mail Addres	s:	jrusso@conch	oresource	s.com		Conditions of	Approval:	Rules	<u>.</u> &	Attached		
Date: 12/13/2011 Phone: 432-212-2399 Attach Additional Sheets If Necessary						Ci	ion per OCD UBMIT REME	KEIAIEDIVIII																	
			•		PI	SOBOSAL N	OT LATER TH	AN:		2RP	- 7	1/8													