

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

<u>NMB1135357544</u>		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company BOPCO, L.P.		Contact Tony Savoie			
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 432-556-8730			
Facility Name Poker Lake Unit #222 on Well Pad #219		Facility Type E&P			

Surface Owner Federal	Mineral Owner Federal	Lease No.
-----------------------	-----------------------	-----------

<u>Poker Lake Unit #219</u>				LOCATION OF RELEASE		<u>30-015-34636</u>		
Unit Letter K	Section 19	Township 24S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy

Latitude N 32.200305 Longitude W 103.922450

NATURE OF RELEASE

Type of Release: Crude oil	Volume of Release: 10 bbls of Crude oil	Volume Recovered: 5 Bbls
Source of Release: Flow Line	Date and Hour of Occurrence 12/13/11 time unknown	Date and Hour of Discovery 12/13/11 12:37 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Tony Savoie	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED
DEC 15 2011

Describe Cause of Problem and Remedial Action Taken.* A 2 3/8" flow developed a leak due to external corrosion, the line was excavated and a repair clamp was placed on the leak.

Describe Area Affected and Cleanup Action Taken.* The spill affected approximately 1000 sq.ft. of caliche well pad and lease road. The free standing fluid was picked up with a vacuum truck and the saturated soil was scraped up and stockpiled on the well pad. The area will be delineated and a remediation plan will be submitted in accordance with the NMOCD recommended guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by District Supervisor Signed By <u>Mike Brannan</u>	
Title: Waste Mgmt. & Remediation Specialist		Approval Date: <u>DEC 19 2011</u>	Expiration Date:
E-mail Address: TASavoie@BassPet.com		Conditions of Approval:	
Date: 12/15/11	Phone: 432-556-8730	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: <u>1/19/2012</u>	

Attached ☐

* Attach Additional Sheets If Necessary

2RP 979