


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

**Release Notification and Corrective Action**

**nmlb/204638693**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating <b>269324</b>	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: JL KEEL A #30 - JL KEEL B #30	Facility Type: Gas Central Tank Battery

Surface Owner: BLM	Mineral Owner: BLM	API No.: 3001521460
--------------------	--------------------	---------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	06	17S	31E	430	South	2250	East	Eddy

Latitude: 32.85744 Longitude: -103.90692

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 72	Volume Recovered: 10
Source of Release: Pipeline	Date and Hour of Occurrence: 10/21/2011 5am	Date and Hour of Discovery: 10/21/2011 5:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher-NM OCD Terry Gregston-BLM	
By Whom? Joe Hernandez	Date and Hour 10/21/2011	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*:

Describe Cause of Problem and Remedial Action Taken.\*: Injection plant lost pressure on line and shut down. Alarm system called and went out to plant. Arrived and shut in line and started looking for leak. Leak was located at a field valve and was on main trunk line. All wells on line were shut in and vacume truck was called to pick up spill.

Describe Area Affected and Cleanup Action Taken.\* : Approximately 10 bbls were picked up. Vacuum truck also tied on to line and drained to prevent more spilling as line drained.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Joe Hernandez	Signed By Approved by District Supervisor:	
Title: Production Foreman	Approval Date: <b>FEB 15 2012</b>	Expiration Date:
E-mail Address: jhernandez@linenergy.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:</b> <b>3/15/2012</b>	Attached <input type="checkbox"/>
Date: 02/02/2012 Phone: 575-942-9492		

\* Attach Additional Sheets If Necessary

**2RP-1022**