


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating 269324	Contact: Joe Hernandez	
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739	
Facility Name: Turner A Battery- Turner A #51	Facility Type: WaterFlood	
Surface Owner: BLM	Mineral Owner: BLM	API No.: 3001528758

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	19	17S	31E	2632	North	75	East	Eddy

Latitude: N32° 49' 16.2" Longitude: W103° 44' 48.2"

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 100	Volume Recovered: 70
Source of Release: Pipeline	Date and Hour of Occurrence: 01/24/2012 9:00am	Date and Hour of Discovery: 01/24/2012 9:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher -NM OCD Terry Gregston-BLM	
By Whom? Joe Hernandez	Date and Hour 01/24/2012 3:00pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: Bolts on clamp rotted. Transfer pump was running and caused water to leak and run down lease road south about 100 yards. Shut down leases and replaced with new piece of pipe and two clamps on both sides. Next day pressure up and no leaks.

Describe Area Affected and Cleanup Action Taken.* : Loco Hills East on 82 to mile marker 137, turn north .3miles leak on west side of lease road. Sucked up water.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCDA rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCDA marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCDA acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Joe Hernandez</i>	OIL CONSERVATION DIVISION	
Printed Name: Joe Hernandez	Signed By <i>Mike Bratcher</i> Approved by District Supervisor:	
Title: Production Foreman	Approval Date: FEB 14 2012	Expiration Date:
E-mail Address: jhernandez@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/01/2012 Phone: 575-942-9492	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: <u>3/14/2012</u>	

* Attach Additional Sheets If Necessary

2RP-1015