

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-31454

Release Notification and Corrective Action

NMLB1204749715

OPERATOR



Initial Report



Final Report

Name of Company Devon Energy 6137	Contact Roger Hernandez
Address P. O. Box 250 Artesia, NM 88211	Telephone No. 575-748-5238
Facility Name Shugart 25 Fed #1	Facility Type Oil Well


Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section 25	Township T18S	Range 31E	Feet from the 1980	North/South Line South	Feet from the 1980	East/West Line West	County Eddy
-------------	---------------	------------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

NATURE OF RELEASE

Type of Release 35 oil & 20 PW	Volume of Release 55bbls	Volume Recovered 55bbls
Source of Release Tank Overflow	Date and Hour of Occurrence 2/2/12, 8:19 AM	Date and Hour of Discovery 2/2/12, 8:19AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Justin Frye, BLM - Eddy County & Mike Bratcher, OCD	
By Whom?	Date and Hour 2/3/12, 8:05 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*  N/A		



Describe Cause of Problem and Remedial Action Taken.\*

Upon arrival at the Shugart 25-1, the lease operator discovered a tank running over resulting in a 55 bbls spill that was kept within the containment, recovering 35 bbls of Oil and 20 bbls of water. Vacuum truck was contacted for clean up.

Describe Area Affected and Cleanup Action Taken.\*

25x70, All Fluid was contained inside steel line containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Gracie Bustamante	Approved by District Supervisor <i>[Signature]</i>	
Printed Name: Gracie Bustamante	Approval Date: FEB 16 2012	Expiration Date: N/A
Title: Contract Field Tech	Conditions of Approval: N/A Final	Attached <input type="checkbox"/>
Date: 2/2/12 Phone: (575) 746-5559		

\* Attach Additional Sheets If Necessary

2RP-1031