

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
**District II** 811 S. 1st  
1301 W. Grand Avenue, Artesia, NM 88210  
**District III**  
1000 Rio Brazos Road, Aztec, NM 87410  
**District IV**  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised March 17, 1999

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-38314

Release Notification and Corrective Action

nmlb/26332867

OPERATOR

☒ Initial Report

☒ Final Report

Name of Company Devon Energy	6137	Contact Roger Hernandez
Address P. O. Box 250 Artesia, NM 88211		Telephone No. 575-748-5238
Facility Name Serene Sisters 25 Fed #1		Facility Type Oil Well

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section 25	Township 18S	Range 31E	Feet from the 400	North/South Line South	Feet from the 400	East/West Line East	County Eddy County
-------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	-----------------------

NATURE OF RELEASE

Type of Release 10 BBLS Produced Water	Volume of Release 10 BBLS	Volume Recovered 10 BBLS
Source of Release Produced Water Tank overflow	Date and Hour of Occurrence 12/26/11, 12:00PM	Date and Hour of Discovery 12/26/11, 12:00Pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Trish BadBear, BLM - Lea County	
By Whom? Roger Hernandez	Date and Hour 12/27/11, 10:30AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

Upon arrival Lease Operator discovered a 10bbl produced water tank overflow, Shut In Well Completely in extreme weather conditions.

Describe Area Affected and Cleanup Action Taken.\*

None - All Fluid was contained inside line containment and vacuum truck was able to recover all 10bbls

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Gracie Bustamante		OIL CONSERVATION DIVISION	
Printed Name: Gracie Bustamante		Approved by <u>Signed By Mike Benavides</u> District Supervisor	
Title: Contract Field Tech	Approval Date: FEB 02 2012	Expiration Date: N/A	
Date: 12/27/11 Phone: (575) 746-5554	Conditions of Approval: N/A Final	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

