

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-38557

Release Notification and Corrective Action

NMLB 1204437755

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy	6137	Contact Roger Hernandez
Address P. O. Box 250 Artesia, NM 88211		Telephone No. 575-748-5238
Facility Name Cotton Draw Unit #156 H		Facility Type Oil Well
Surface Owner FED	Mineral Owner	Lease No.

LOCATION OF RELEASE

Unit Letter A	Section 35	Township 24S	Range 31E	Feet from the 200'	North/South Line North	Feet from the 660'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release 20 Bbls	Volume Recovered 15 bbls 5BO, 10BPW
Source of Release Flowline	Date and Hour of Occurrence 1-25-12 1:30 AM	Date and Hour of Discovery 1-25-12 1:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM (TrishBadBear) and OCD (Mike Bratcher)	
By Whom? Roger Hernandez	Date and Hour 1-25-12 BLM 1:50 PM; 1-25-12 OCD 2:02 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		<div>RECEIVED JAN 27 2012 NMOCD ARTESIA</div>

Describe Cause of Problem and Remedial Action Taken.*

Knick in flowline cause unknown, called vacuum truck to pick up fluids and called company for remediation recommendation.

Describe Area Affected and Cleanup Action Taken.*

Affected area is 90'x490' (L-Shape) waiting to hear what type of remediation is going to be necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Adrienne Verkler	Approved by <u>Signed By: [Signature]</u>	
Printed Name: Adrienne Verkler	FEB 13 2012	
Title: Field Tech II	Approval Date:	Expiration Date:
Date: January 26, 2012 Phone: (575) 748-0174	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**
3/13/2012

2RP-1009