Submit One Copy To Appropriate District State C	of New Mexico	Form C-103
Office District 1 Energy, Minera	ls and Natural Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II 811 S First St , Artesia, NM 88210 OIL CONSEI	RVATION DIVISION	30-015-22212
District III 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	,	o. otate on a das Boase No.
87505	ON MEN I C	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Anadarko Pardue Farms ANQ Com
PROPOSALS)	RECEINED	8. Well Number: 1
1. Type of Well: Oil Well Gas Well	1 LUSHERM PRAME	
2. Name of Operator Yates Petroleum Corporation	MAY 16 2012	9. OGRID Number 025575
3. Address of Operator		10. Pool name or Wildcat
105 South 4 th Street, Artesia, NM 88210	NMOCD ARTESIA	Dagger Draw; Upper Penn, North
4. Well Location		
Unit Letter \underline{F} : 2130 feet from the Nor	th line and <u>1980</u>	feet from the West line
Section 27 Township 21S Range 24E NMPM County: Eddy 11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3680'GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
12. Check Appropriate Box to indicate Nature of Notice, Report of Other Bata		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
OTHER:		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4" above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and		
other production equipment.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location.		
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.) All other environmental concerns have been addressed as per OCD rules.		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
retrieved flow lines and pipelines.		
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well		
location, except for utility's distribution infrastructure.		
Active battery on tocation in need of reclamation. Will reclaim after last well going to batter when all work has been completed, return this form to the appropriate District office to schedule an inspection. is Plugged.		
JIGNATURE Chave Donto	TITLE <u>Production Forem</u>	an DATE <u>5/14/2012</u>
TYPE OR PRINT NAME Chance Sexton E-MAIL	: chances@yatespetroleum.con	PHONE: <u>575-748-1471</u>
For State Use Only	<i>β</i> [±]	Λ\.
	MEASIE	-1-1
APPROVED BY:	_TITLETITLE	DATE 5/17/2012
Conditions of Approval (if any):		/ /

YaTes Petroleum Coop.

Anadarko Pardur Farms ANG Com. #1 30-015-22212 F-27-21-24

DENIED - Junk pipe and misc. Jank on toxation needs to be aloned up.

Electric auble autlings (RC +Ct, piece of coller alongs.)

and junk around P/4 Marker needs

to be removed.

Active buttery on Leastion Ok for release.

Philadei 5/17/2012