

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NMLB 12150-50616

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Apache Corporation	873	Contact	Natalie Gladden
Address	PO Box 1849 Eunice, NM 88231		Telephone No.	575-390-4186
Facility Name	NB Tween #16		Facility Type	Production well

Surface Owner	Concho Resources	Mineral Owner	State	API No.	30-015-38406
---------------	------------------	---------------	-------	---------	--------------

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	25	17S	28E	1650'	FNL	990'	FEL	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	10	Volume Recovered	0
Source of Release	BOP Failure	Date and Hour of Occurrence	3/12/12	Date and Hour of Discovery	03/12/12
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Bratcher		
By Whom?	Natalie	Date and Hour	3/21/02 824am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*
Workover rig on well shut in BOP Valves the evening before but it did not seal correctly. Seals were replaced and fluid was recovered.

Describe Area Affected and Cleanup Action Taken.*
Site will be remediated and the NMOCD Guidelines will be followed to closure of this release.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	Signed By:	
Title: EHS Environmental Tech	Approved by Environmental Specialist:	Approval Date: MAY 29 2012
E-mail Address: natalie.gladden@apachecorp.com	Expiration Date:	Conditions of Approval:
Date: 3/26/12 Phone: 575-390-4186	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 6/29/2012	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-1134