

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JUN 14 2012

Form C-141  
Revised August 8, 2011

NMOC DISTRICT OFFICE IN ARTESIA

Submit to the appropriate District Office in accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

JMW 1217347760

OCRTD# 271841/OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ALAMO PERMIAN RESOURCES, LLC	Contact	STEVEN MASTIN
Address	415 W. WALL ST. SUITE 500	Telephone No.	432 557 5847
Facility Name	EMPIRE J FEDERAL #3	Facility Type	WELL

Surface Owner	FEDERAL	Mineral Owner	FEDERAL	API No.	30-015-00169
---------------	---------	---------------	---------	---------	--------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	1	18S	26E	2304	N	330	E	EDDY

Latitude 32.7723 Longitude -104.32915

### NATURE OF RELEASE

Type of Release: Oil and Water	Volume of Release: EST 3 bbls Oil, 11 bbls Water	Volume Recovered: 2 bbls Oil
Source of Release: Backside casing valve.	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 6/14/2012
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Stewart	
By Whom? Jennifer Van Curen, BLM	Date and Hour 6/14/2012	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Cause of problem: Discharge from backside casing valve.  
Remedial Action Taken: Vacuum trucks dispatched to suck up standing fluid.

Describe Area Affected and Cleanup Action Taken.\*

Localized area around wellsite, vacuum trucks picked up 2 bbls of standing oil. Scraping and proper disposal of remaining fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

### OIL CONSERVATION DIVISION

Signature: <i>Tom Fulvi</i>	Approved by Environmental Specialist: <i>Mike Stewart</i>	
Printed Name: TOM FULVI	Approval Date: JUN 21 2012	
Title: REGULATORY AFFAIRS COORDINATOR	Expiration Date:	
E-mail Address: tfulvi@alamoresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06/14/2012 Phone: 432 664 7659		

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules &  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:

7/21/12

2RP-1184