


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Release Notification and Corrective Action

nJMW1217354614 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: Linn Operating 269324	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Skelly # 247	Facility Type: Oil

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3001528788
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	21	17S	31E	1110	South	2515	West	Eddy

Latitude: 32.8158761231942 Longitude: -103.875077780113

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 30 gal	Volume Recovered: 0
Source of Release: Pipeline	Date and Hour of Occurrence: 06/04/2012 7am	Date and Hour of Discovery: 06/04/2012 7:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher-NM OCD Terry Gregston- BLM	
By Whom? Joe Hernandez	Date and Hour 06/04/2012 1:30pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: Injection header north of s.u. 247, 3 inch steel line had pin-hole spray 30x20 ft on ground. Shut in header to stop and repair leak. Pin hole caused by corrosion.

Describe Area Affected and Cleanup Action Taken.* : sprayed 30 x 20 ft on ground. Further remedial action pending...

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Joe Hernandez	Signed By	
Title: Production Foreman	Approved by District Supervisor:	
E-mail Address: jhernandez@linenergy.com	Approval Date: JUN 21 2012	Expiration Date:
Date: 06/21/2012 Phone: 575-942-9492	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

7/21/12

2RP-1189