

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

nJMW 1218036666 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company Apache Corporation 873	Contact Natalie Gladden
Address PO Box 1849 Eunice NM 88231	Telephone No. 575-390-4186
Facility Name NFE Federal #6	Facility Type Production well

Surface Owner BLM	Mineral Owner State	Lease No. 30-015-37361
-------------------	---------------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	8	17S	31E	1650	FSL	990	FEL	Lea Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release Oil/Water	Volume of Release 20	Volume Recovered 15
Source of Release Flowline	Date and Hour of Occurrence 06/22/2012	Date and Hour of Discovery 06/22/12 5pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Natalie Gladden	Date and Hour 06/22/12 7pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The steal flowline was found by a Lynn Energy pumper. Leak was due to corrosion. The standing fluid was recovered by a vacuum truck. Location was backdragged until one-call was made and cleared.		
Describe Area Affected and Cleanup Action Taken.* The location will be remediated to meet the NMOCD and BLM Remediation Standards to closure.		

RECEIVED  
JUN 27 2012  
NMOCD ARTESIA

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Natalie Gladden	OIL CONSERVATION DIVISION Signed By: [Signature]	
Printed Name: Natalie Gladden	Approved by District Supervisor:	
Title: EHS Environmental Tech	Approval Date: JUN 28 2012	Expiration Date:
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/22/12 Phone: 575-390-4186		

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules &  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:

7/28/12

2RP-1194