


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit to appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

nJMW1219531844		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: Linn Operating 269324		Contact: Joe Hernandez		
Address: 2130 W. Bender Hobbs, NM 88240		Telephone No.: 575-738-1739		
Facility Name: Turner B Battery Oil Tank- Turner B #95		Facility Type: Battery		
Surface Owner: Federal		Mineral Owner: Federal		API No.: 3001526612

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	20	17S	31E	2610	South	1000	West	Eddy

Latitude: 32.8199711236509 Longitude: -103.897239412252

NATURE OF RELEASE

Type of Release: Oil / Produced Water	Volume of Release: 60 / 249	Volume Recovered: 45 / 220
Source of Release: Tank	Date and Hour of Occurrence: 07/06/2012 6am	Date and Hour of Discovery: 07/06/2012 6:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher - NM OCD Terry Gregston- BLM	
By Whom? Joe Hernandez	Date and Hour 07/06/2012 9am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: Pump at the Turner Russell Injection plant went down and skim tanks filled up and sent water to Turner B Batter and over ran the system. Alarm system did not call out. Haarmeyer was called out checked out system and said it was working.		
Describe Area Affected and Cleanup Action Taken.* : North of injection plant 60 x 30 ft running west to main road and south joining Russell Turner Injection spill. Water was pulled out of dike and road.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature:	OIL CONSERVATION DIVISION	
Printed Name: Joe Hernandez	Approved by District Supervisor:	Signed By
Title: Production Foreman	Approval Date: JUL 13 2012	Expiration Date:
E-mail Address: jhernandez@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 07/09/2012 Phone: 575-942-9492		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

8/13/12

2RP-1223