

REVISED

RECEIVED

JUL 16 2012

Form C-141  
Revised October 10, 2003

NMOCD ARTESIA

District Office in  
accordance with 19.15.29 NMAC

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

## Release Notification and Corrective Action

nJMW 12214 29082

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating 269324	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: JL Keel B #77	Facility Type: Injection

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3001528279
------------------------	------------------------	---------------------

## LOCATION OF RELEASE

Unit Letter H	Section 08	Township 17S	Range 31E	Feet from the 1930	North/South Line North	Feet from the 714	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: 32.85099 Longitude: -103.88486

## NATURE OF RELEASE



Type of Release: Produced Water	Volume of Release: 21	Volume Recovered: 0
Source of Release: Pipeline	Date and Hour of Occurrence: 07/07/2012 1pm	Date and Hour of Discovery: 07/07/2012 1:30pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher-NM OCD Terry Gregston-BLM	
By Whom? Joe Hernandez	Date and Hour 07/09/2012 9am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*:

Describe Cause of Problem and Remedial Action Taken.\*: Drove to location, noticed water coming out of ground from 2" fiberglass injection line. Went to Keel B #76 well to close valve to isolate line.

Describe Area Affected and Cleanup Action Taken.\*: 2' x 300yd Cleanup action pending....

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Joe Hernandez	Signed By  Approved by District Supervisor.	
Title: Production Foreman	Approval Date: AUG 01 2012	Expiration Date:
E-mail Address: jhernandez@linenergy.com Date: 07/13/2012 Phone: 575-942-9492	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules &  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:

9/1/12

2RP-1233