

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

nJMW1219528557  
Name of Company: BOPCO, L.P. 260737  
Address: 522 W. Mermod, Suite 704  
Carlsbad, N.M. 88220  
Facility Name: Poker Lake Unit 213 SWD  
Facility Type: Salt Water Disposal Tank Battery  
Surface Owner: Federal  
Mineral Owner: Federal  
API No. 30-015-33859

**LOCATION OF RELEASE**

Unit Letter P	Section 18	Township 24S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude: N 32.212384 Longitude: W 103.914812

**NATURE OF RELEASE**

Type of Release Produced Water Source of Release 3" Poly Line	Volume of Release 60 bbls Date and Hour of Occurrence: 6/23/12 Approximately 11:00 p.m.	Volume Recovered 10 bbls Date and Hour of Discovery: 6/23/12 Approximately 11:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Emergency #104	
By Whom? Tony Savoie	Date and Hour 6/24/12 11:15 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		<b>RECEIVED</b> JUL 09 2012 NMOCD ARTESIA

**Describe Cause of Problem and Remedial Action Taken.\***

A transport truck owned by Horizon Trucking ran over the S.W. corner of the 0 perm containment breaking a 3" poly line. The water transfer pump was shut down by the night pumper. The broken line and fitting were repaired the next day.

**Describe Area Affected and Cleanup Action Taken.\***

Approximately 4050 sq. ft. of caliche pad and road along with approximately 6900 sq. ft. of pasture land was affected by the release. The water standing on the caliche pad area was removed with a vacuum truck. All of the fluid released into the pasture soaked into the ground. The spill area was reviewed with the BLM on 6/27/12. A remediation plan will be submitted along with the BLM recommendation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Signed By: M. L. Brannon	
Title: Waste Mgmt. and Remediation Specialist	Approved by Environmental Specialist:	Approval Date: JUL 13 2012
E-mail Address: tasavoie@basspet.com	Conditions of Approval:	Expiration Date:
Date: 7/9/12 Phone: 432-556-8730	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 8/13/12	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

2RP-1221