

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NMLB 10314-50923

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG Operating LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 1300 Midland, Texas 79701	Telephone No.	(432) 230-0077
Facility Name	Red Lake Sand Unit #45	Facility Type	Steel Flowline

Surface Owner: State	Mineral Owner	Lease No. (API#) 30-015-33198
----------------------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	20	17S	28E					Eddy

Latitude 32 48.688 Longitude 104 11.678

NATURE OF RELEASE

Type of Release: Produced Fluid	Volume of Release 10 bbls	Volume Recovered 0 bbls
Source of Release: Steel Flowline	Date and Hour of Occurrence 08/29/2010	Date and Hour of Discovery 08/29/2010 11:30 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Josh Russo	Date and Hour 3/15/10 4:59 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

A hole developed in the Red Lake Sand Unit #45 steel flowline due to corrosion. The steel flowline has been repaired and we are in the process of replacing all steel flowlines to poly flowlines.

Describe Area Affected and Cleanup Action Taken.*

Tetra Tech personal inspected the site and collected samples to define the spills extent. Soil that exceeded the RRAL was removed to the depths stated in the approved work plan and hauled away for proper disposal. The site was then brought up to surface grade with clean backfill material. Tetra Tech has prepared a closure report and submitted it to the NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Ike Tavarez

Title: Project Manager

E-mail Address: Ike.Tavarez@TetraTech.com

Date: 1-25-12

Phone: (432) 682-4559

OIL CONSERVATION DIVISION

Signed By Mike Benner
Approved by District Supervisor:

Approval Date: **AUG 13 2012**

Expiration Date: N/A

Conditions of Approval: N/A

Attached ☐

* Attach Additional Sheets If Necessary

2RP-476