District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Revised August 8, 2011

Form C-141

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action												
nJMW1223641037						OPERATOR						
Name of Company: BOPCO, L.P. 260737 Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220						Contact: Tony Savoie Telephone No. 575-887-7329						
Facility Name: Remuda Basin Battery #1 Water Transfer Line Approximately 1250 ft. East of the battery.						Facility Type: Exploration and Production						
Surface Owner: State of N.M. Mineral Owner						: State of N.M. AI			API No	No. 30-015-03691		
· 				LOCA'	ΓIO	ON OF RELEASE						
Unit Letter I	Section 24	Township 23S	Range 29E			h/South Line	Feet from the	East/West Line		County Eddy		
Latitude: N 32.288222 Longitude: W 103.932289 NATURE OF RELEASE												
Type of Release: Produced water										e Recovered: None		
Source of Release: 3" poly line						Date and Hour of Occurrence: Date			Date and	nd Hour of Discovery: 2 10:00 a.m.		
Was Immediate Notice Given? ☐ Yes ☐ No ☒ Not Required						If YES, To Whom?						
By Whom?						Date and Hour						
Was a Watercourse Reached? Yes No						If YES, Volume Impacting the Watercourse. RECEIVED						
If a Watercourse was Impacted, Describe Fully.*										AUG 2 (
Describe Cause of Problem and Remedial Action Taken.* The 3" poly line split, the bad section of pipe was replaced.									1	VMOCD A	RTESIA	
Describe Area Affected and Cleanup Action Taken.* Approximately 1800 sq.ft. of pasture was lightly misted at the release point, the fluid traveled down a caliche road, then exited the road into the pasture. Approximately 600 sq.ft. of road and approximately 960 sq.ft. of pasture was affected by the run-off areas. The area was reviewed prior to the release date; it was noted on 4/18/12 that there had been several reports of trucks dumping produced water on the road from the tank battery to Rawhide road. The affected area in the pasture will be remediated in accordance to the NMOCD guidelines.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
						OIL CONSERVATION DIVISION						
Signature: / Ony Sauce Printed Name: Tony Savoie						Approved by Environmental Specialist: Signed By Mily Beauty						
Title: Waste Management and Remediation Specialist						Approval Date: AUG 2 2 2012 Expiration Date:						
E-mail Address: tasavoie@basspet.com						Conditions of Approval:				Attached		
Date: 8/15/12 Phone: 432-556-8730										Attached []		
Attach Additional Sheets If Necessary						Remediation per OCD Rules & 2RP-1258 Guidelines. SUBMIT REMEDIATION					258	لــــ

PROPOSAL NOT LATER THAN: Sept. 22, 2012