District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

AUG 02 2012

RECEIVED

Form C-141 Revised October 10, 2003

NMOGDI APTE STATE District Office in accordance with 19 15.29 NMAC

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action												
MM		1223		19		OPERATOR					Final Report	
		inn Operatin		2693		Hernandez	20					
Address: 2130 W. Bender Hobbs, NM 88240 Telephone No.: 575-738-1739  Facility Name: State A & B Battery -Skelly Unit #4 (P&A) Facility Type: Battery												
Surface Owner: Federal Mineral Owner: F												
Unit Letter   Section   Township   Range   Feet from the   North/South Line   Feet from the   East/West Line   County											_	
Unit Letter B	Section 21	Township 17S	Range 31E	810		South Line North	Feet from the 1980	East/West Lin East	e County	Eddy		
Latitude: 32.8250951598049 Longitude: -103.872607813234												
Type of Release: Produced water  NATURE OF RELEASE  Volume of Release: 4 bbls  Volume Recovered: 1 bbl												
Source of Release: Polyline							Volume of Release: 4 bbis   Volume Recovered: 1 bbi     Date and Hour of Occurrence:   Date and Hour of Discovery:					
						07/27/2012 11:00 AM 07/27/2012 11:30 AM						
Was Immediate Notice Given?  ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? Mike Bratcher - NMOCD Terry Gregston - BLM						
By Whom? Gary Wink						Date and Hour 07/27/2012 12:00 AM  If YES, Volume Impacting the Watercourse.						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Vo	iume Impacting tr	ie Watercourse	•			
If a Watercourse was Impacted, Describe Fully.*:												
Describe Cause of Problem and Remedial Action Taken.*: 2" polyline had a small, dime size hole. It looked like it was run over as it had tire marks.												
Called gang to repair line. Further remedial action pending												
Describe Area Affected and Cleanup Action Taken. *: Spill sight 75' west of SU #4 P&A. M&S picked up 1 bbl.												
Describe Area America and Creanup Action Taxen Spin signi 75 west of 50 ## F&A. M&S picked up 1 obt.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger												
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability												
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other.												
federal, state, or local laws and/or regulations.												
						OIL CONSERVATION DIVISION						
Signature: Signature									1	/ ,	10	
Printed Name: Joe Hernandez						Approved by District Supervisor: Signed By Mile Beautiful						
Title: Production Foreman						pproval Da	UG 0 9 201	2 Expiration	Expiration Date:			
E-mail Address: jhernandez@linnenergy.com						Conditions of Approval:			Attached			
Date: 08/02/20	012	Ph	one: 575-9	942-9492		onditions of	търгота.		Allactied			
Attach Additional Sheets If Necessary  Remediation per OCD Rules & 2RP-1249												
					1101			TION			~ /	

Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: