District 1
1625 N. French Dr , Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Division
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action													
MICH	W 122	22418	154			OPERA	ror	[X Initia	al Report		Final Report	
Name of Company SM ENERGY COMPANY 154903 Contact VICKIE MARTINEZ													
Address 3300 N "A" ST BLDG 7-200 MIDLAND, TX 79705 Telephone No. (432)688-1709 Facility Name PDU TRACT 2 30-015-26112 Facility Type BATTERY													
Surface Owner BUREAU OF LAND MANAGE WEINET Owner BUREAU OF LAND MANAGEMENTPI No. NMNM88491X													
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the	ļ	South Line	Feet from the		est Line	County	County		
О	26	19S	29E	330	SOUT	Ή	1980	EAST		EDDY	EDDY		
		•	La	titude		Longitud	e	•		, ,		***************************************	
NATURE OF RELEASE													
Type of Rele		Volume of Release 100 BBLS Volume Recovered 72 BBLS											
Source of Re				Date and Hour of Occurrence 7/21/1 Date and Mour of Discovery SAME									
Was Immedia	ate Notice C	iven?	If YES, To Whom? JIM AMOS WITH BLM										
By Whom? F	RILL HEA	Date and Hour 7/21/12 1:22 PM											
By Whom? BILL HEARNE Was a Watercourse Reached?							lume Impacting t		course.	DE			
☐ Yes 🗶 No										HE	CE	IVED	
If a Watercourse was Impacted, Describe Fully.*										AI	IG OG	2012	
N/A				•					· · · · · · ·	2012			
										NMO	CD A	RTESIA	
Describe Cause of Problem and Remedial Action Taken.*													
A RESTRICTED WATER DUMP LINE ON A 4'X10' FWKO WAS CAUSE OF THE PROBLEM. SM ENERGY WILL BE TURNING													
THIS OVER TO TETRA TECH FOR FURTHER EVALUATION.													
Describe Area Affected and Cleanup Action Taken.*													
SPILL AREA: 60'X90' = 5400 SQ FT (DIKE AREA), PASTURE: 30'X75' = 2250 SQ FT													
I hereby certif	fy that the in	nformation giv	en above	is true and compl	ete to the	e best of my l	cnowledge and ur	nderstand	that pursu	ant to NMC	CD rule	es and	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, state, on local laws and/or regulations.							OIL CONSERVATION DIVISION						
Signature: VIII IIIIII						OIL CONSERVATION DIVISION							
						Approved by Environmental Specialist:							
Printed Name:	VICKIE N	MARTINEZ		A	pproved by E	invironmental Sp	ecialist:						
Title: ENGINEER TECH II						Approval Date 0 9 2012 Expiration Date				ate:			
E-mail Addres	s: VMAR7	TINEZ@SM	Y.COM	C	Conditions of Approval:								
										Attached			
Date: 08/02/2		s If Necessa		<u>(432)688-1709 </u>		Domo diati	an nor OCD D	uloc O	İ	2	017	17/1	
Attach Additional Sheets If Necessary Remediation per OCD Rules & 2KP-1251 Guidelines. SUBMIT REMEDIATION												1251	

PROPOSAL NOT LATER THAN: