


District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit to appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

*NTMW 12222 54957*

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating	Contact: Gary Wink
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575738-1739
Facility Name: Max Friess "MA" Battery	Facility Type: Battery/Max Friess MA #006
Surface Owner: /Federal	Mineral Owner: Federal
API No.: 3001526882	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	30	17S	31E	1270	North	1460	East	Eddy

Latitude: 32.8092955240438 Longitude: -103.905242165769

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 65 bbls	Volume Recovered: 50 bbls
Source of Release: Water transfer line	Date and Hour of Occurrence: 08/07/2012 7:20 AM	Date and Hour of Discovery: 08/07/2012 12:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Terry Gregston - BLM, Mike Bratcher - NMOCD	
By Whom? Joe Hernandez and Gary Wink	Date and Hour 08/07/2012 2:45 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: Dirt crew was covering open space hole. They filled hole and it is possible that lines weren't packed good enough. Fiberglass line, was cracked which caused water to come out of water transfer line for Max Friess Battery.		
Describe Area Affected and Cleanup Action Taken.*: The area affected was approx. 40X70. Blade Services dug around lines where water was leaking and started cleaning up contaminated dirt. Further remedial action is pending.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Gary W. Wink</i>	OIL CONSERVATION DIVISION	
Printed Name: Gary W. Wink	Approved by District Supervisor:	Signed By <i>Mike Bratcher</i>
Title: Production Foreman	Approval Date: <b>AUG 09 2012</b>	Expiration Date:
E-mail Address: gawink@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 08/08/2012 Phone: 575-390-3477		

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules &  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:

9/9/12

*2RP-1254*