


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1224940265 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	16696	Contact	Christopher Jones
Address	1502 W. Commerce Drive, Carlsbad, NM		Telephone No.	(575) 628-4121
Facility Name	McMillan 24 State #2		Facility Type	Well

Surface Owner	State of NM	Mineral Owner	State of NM	Lease No.	API# 30-015-32336
---------------	-------------	---------------	-------------	-----------	-------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	24	20S	26E	1980	South	990	East	Eddy County, NM

Latitude N 32.55749 Longitude W 104.33235

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	733 bbls	Volume Recovered	100 bbls
Source of Release	ROD BOP rubber failure	Date and Hour of Occurrence	06/14/2012 @ 8:00 am	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Chris Jones	Mike Bratcher-NMOCD			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Date and Hour 06/14/2012 @ 2:40 pm			
If YES, Volume Impacting the Watercourse.					

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


ROD BOP rubber failure caused 773 bbls of produced water to leak onto the ground. 100 bbls of produced water were recovered via vacuum truck. Remediation will be performed according to a NMOCD-approved remediation plan.

Describe Area Affected and Cleanup Action Taken.*

The area affected is approximately 700' x 280'. 100 bbls of produced water were recovered and additional remediation will be performed according to a NMOCD-approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 

Printed Name: Christopher Jones

Title: HES Specialist

E-mail Address: Christopher_Jones@oxy.com

Date: Phone: (575) 328-4121

Approved by District Supervisor:

Signed By Mike Bratcher

SEP 05 2012

Approval Date:

Expiration Date:

Conditions of Approval:

Attached ☐

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION**

PROPOSAL NOT LATER THAN:

October 5th, 2012

2RP-1274