

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

nJMW 1224153124  
**OPERATOR** ☒ Initial Report ☐ Final Report  
Name of Company: BOPCO, L.P. 260737 Contact: Tony Savoie  
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Telephone No. 575-887-7329  
Facility Name: PLU Peirce Canyon 17 Federal #1H Facility Type: Exploration and Production  
Surface Owner: Federal Mineral Owner: Federal API No. 30-015-36635

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	17	25S	30E	350	South	350	East	Eddy

Latitude N 32.123902 Longitude W 103.896282

**NATURE OF RELEASE**

Type of Release: Crude Oil	Volume of Release: 10 bbls.	Volume Recovered: None
Source of Release: A 3" line going from the process vessels to the tanks.	Date and Hour of Occurrence: 7/31/12 Approximately 12:00 p.m.	Date and Hour of Discovery: 7/31/12 at 2:20 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos BLM	
By Whom? Tony Savoie	Date and Hour: 7/31/12 2:27 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A 3" line going from the heater to the tanks split at a seam in the pipe. The entire section of pipe was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The split was on top of the pipe, the released fluid misted an area covering approximately 36,000 sq. ft. There was less than 1/4" of soil saturation out to a distance of 300 ft. from the release point. The vegetation had a very slight mist out to a total distance of 420 ft. The area affected appears to have been a frak pond used during the drilling operations. The reclaimed area measured approximately 375 ft. East by West and 510 ft. North by South. The affected area will be remediated in accordance to the NMOCD and BLM guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by Environmental Specialist: Signed By Mike Brannon	
Title: Waste Management and Remediation Specialist	Approval Date: AUG 28 2012	Expiration Date:
E-mail Address: tasavoie@basspet.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:</b>	Attached <input type="checkbox"/>
Date: 8/15/12	Phone: 432-556-8730	

\* Attach Additional Sheets If Necessary

9-28-12

2RP-1266

