

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

AUG 27 2012

NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Send 3 copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

nJMW1225450335

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Folk Federal B Tank Battery	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#)	30-015-36862
		Closest well location	

LOCATION OF RELEASE



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	17	17S	29E					Eddy

Latitude 32.83623 Longitude 104.09164

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	130bbls	Volume Recovered	129bbls
Source of Release	Produced water tank	Date and Hour of Occurrence	08/18/2012	Date and Hour of Discovery	08/18/2012 12:00 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD Jim Amos-BLM Terry Gregston-BLM		
By Whom?	Michelle Mullins	Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
We had a power failure from a lighting storm which disabled our alarm system at the Folk Federal B Tank Battery allowing the produced water tank to overflow inside the facility.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 130bbls of produced water were released from the produced water tank and we were able to recover 129bbls with a vacuum truck. This is a 40 mil lined facility. All free fluid has been recovered and the contaminated gravel has been removed from the facility. We have added fresh gravel to the facility as necessary. The facility has been returned to its prior condition.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature:		Approved by District Supervisor:	Signed By 
Printed Name:	Josh Russo	Approval Date:	SEP 10 2012
Title:	HSE Coordinator	Expiration Date:	N/A
E-mail Address:	jrusso@conchoresources.com	Conditions of Approval:	N/A
Date:	08/27/2012	Phone:	432-212-2399
		Attached	<input type="checkbox"/>

\* Attach Additional Sheets If Necessary

ZRP-1278