<u>District I</u> 1625 N. French Dr , Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

RECEIVED

Form C-141 Revised March 17, 1999

AUG 28 2012

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back side of form

Release Notification and Corrective Action									
	OPERATOR		Final Repor						
Name of Company Devon Energy 613	Contact	Tracy Kidd							
Address P. O. Box 250 Artesia, NM 88211	Telephon	e No. 575-513-0628							
Facility Name Snapping 2 State 4H	Facility T	Facility Type Oil Well							
Comforce Overnor	4:1 O	T NT.	 -						

Address P. O. Box 250 Artesia, NM 88211					1	Telephone No. 5/5-513-0628					
					Facility Type Oil Well						
Surface Owner Mineral Own				Owne							
LOCATION OF RELEASE API#30-015-39071											
Unit Letter P	Section 2	Township 26S	Range 31E	Feet from the 330		South Line	Feet from the 735	East East	/West Line	County Eddy	
	<u></u>	<u> </u>		D. A. (TE				<u> </u>			
Type of Release SPILL Volume of Release 20bbls of Oil Volume Recovered 10bbls of Oil											
Source of Release Tank Overflow					Date and Hour of Occurrence Date and Hour of Discovery 08/2 08/22/12, 7:30am 7:30am						
Was Immediate Notice Given? Ves No Not Required Not Required Was Immediate Notice Given? If YES, To Whom? OCD – Mike Bratcher											
By Whom?						Date and Hour 08/22/12, 8:45am					
Was a Watercourse Reached? ☐ Yes ☒ No					If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*											
N/A											
Describe Cause of Problem and Remedial Action Taken.* At the Snapping 2 State 4H battery, a miscommunication between two well watchmen led to the overflow of a frac tank, resulting in an oil spill of 20bls.											
Describe Area Affected and Cleanup Action Taken.* The day well watcher noticed that the well had loaded up and was not producing. He switched all of the production from the equipment to a frac tank in order to release pressure, so the well would began producing. Upon completion of his shift that evening, he notified the night well watcher of the changes. The night well watcher did not understand the instructions received and continued to monitor the production tanks. He was under the impression that his											
levels in the production tanks at the battery were fine, so he went to sleep. The night watchman woke up in the morning to discover that the frac tank was overflowing. The overflow result in a spill of 15bbls of oil on the location and 5bbls of oil in the pasture off the side of location. A vacuum truck was able to recover 10bbls and return the oil to the oil tank. The Devon PIC has made arrangements to remove the oily dirt and replace it.											
regulations all public health of should their of	operators a or the environations had ment. In ac	are required to onment. The a ave failed to a ddition, NMO	report and acceptance dequately CD accept	d/or file certain re e of a C-141 repor investigate and re	lease no t by the mediate	otifications and NMOCD materials	d perform correct rked as "Final Roon that pose a thr	tive ac eport" of eat to g	tions for rele does not relie round water.	uant to NMOCD rules and ases which may endanger eve the operator of liability surface water, human health impliance with any other	
							OIL CON	SER \	ATION	DIVISION	
Signature: Gracie Bustamante A				Approved by District Supervisioned By Mile Banana							
Printed Name:					$-\!$	SED 1 0 2012					
Title: Adm Fi	eld Support	<u> </u>			A	Approval Date	CLI IO L	, , _	Expiration E		
Date: 08/24/12	Phone:	(575) 746-5	561		C	Conditions of	Approval:			Attached	

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & **Guidelines. SUBMIT REMEDIATION** 2RP-1280

PROPOSAL NOT LATER THAN: