


District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

2 Copies to appropriate
office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1225452591 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd. 16696	Contact	Christopher Jones
Address	1502 W. Commerce Drive, Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Rogers #003	Facility Type	Gathering
Surface Owner	Mineral Owner	Lease No. API#30-015-39849	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	23	18S	26E	1650	N	990	E	Eddy County, NM

Latitude N 32.73586° Longitude W 104.34734°

NATURE OF RELEASE

Type of Release	Oil and Produced Water	Volume of Release	290 bbls	Volume Recovered	1 bbl
Source of Release	Portable test equipment failure	Date and Hour of Occurrence	08/13/2012	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD		
By Whom?	Chris Jones	Date and Hour	08/14/2012 @ 7:35 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A portable test equipment failure caused 290 bbls of oil and produced water to leak onto the ground. 1 bbl of liquid was recovered via vacuum truck. Remediation will be performed according to a NMOCD-approved remediation plan.

Describe Area Affected and Cleanup Action Taken.*

The area affected is approximately 60' x 260'. 1 bbl of oil and produced water were recovered and additional remediation will be performed according to a NMOCD-approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Christopher Jones	Approved by District Supervisor:	Signed By <i>M. Bratcher</i>	
Title: HES Specialist	Approval Date: SEP 10 2012	Expiration Date:	
E-mail Address: Christopher.Jones@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date:	Phone: (575) 328-4121		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:

October 10, 2012

2RP-1279