District I 1625 N French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 RECEIVED

AUG 21 2012

Form C-141 Revised October 10, 2003

NMOCD ARTESIA

Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

. /			Rele	ease Notific	atioı	a and Co	orrective A	ction	į.				
nTUlali	72480	OPERATOR			☑ Initi	al Report	П	Final Report					
Name of Co		Contact		at Ellis									
								230-00	77				
Facility Name Burch Keely Unit #632							oe We	ell pad					
Surface Owner Federal Mineral Owner							Lease No. (API#) 30-015-40327						
						N OF RE	LEASE						
Unit Letter M					North/	/South Line   Feet from the   Eas		East/W	West Line County Eddy				
Latitude 32 48.855 Longitude 104 02.066													
NATURE OF RELEASE													
Type of Release Produced water							Volume of Release 134bbls Volume Recovered 130bbls						
Source of Release BKU #112 injection line										Date and Hour of Discovery			
Was Immediate Notice Given?							08/14/2012 08/14/2012 If YES, To Whom?				m.		
was illilledii	✓ Yes ☐ No ☐ Not Required						WHOIII:	Mike B	ratcher-O	CD			
									Amos-BLN			1	
D. 11/1 0 I 1 P							Terry Gregston-BLM Date and Hour 08/15/2012 8:50 a.m.						
By Whom? Josh Russo Was a Watercourse Reached?							olume Impacting the						
Yes No													
If a Watercou	rse was Imp	acted, Descri	be Fully.*	,									
Describe Cau	se of Proble	m and Remed	lial Action	Taken.*					****				
_													
			r accident	ly hit a buried inje	ction li	nc from the I	BKU #112 causing	g the rele	ase of flui	d onto the s	ite. The	e line has	
been repaired	and returne	d to service.										ļ	
Describe Area	Affected a	nd Cleanup A	ction Tak	en.*					<del></del>				
Initially 134h	bls were rel	eased from the	e injection	line and we were	able to	recover 1301	ohls with a vacuum	n truck	The relea	sed fluid wa	s contai	ined in a 10'	
				fluids were remove									
Tech sampled	the spill are	ea and we hav	e backfill	ed the site in prepa	ration	of the drilling	rig.						
I hereby certi	fy that the ir	nformation giv	en above	is true and comple	te to th	ne best of my	knowledge and ur	nderstan	d that purs	uant to NM	OCD ru	les and	
regulations al	l operators a	re required to	report an	d/or file certain rel	ease no	otifications ar	nd perform correct	ive actio	ons for rele	eases which	may en	danger	
				e of a C-141 report									
				investigate and rer tance of a C-141 re									
federal, state,													
							OIL CONSERVATION DIVISION						
Signature:	//	9	/5		-								
Printed Name: Josh Russo A							District Superviso	٠	ر	. J. J	/		
							Approved by District Supervisor: Signed By Mile Benesics						
Title: HSE Coordinator A						Approval Date: Expiration Date:							
E-mail Addres	ss:	jrusso@concl	oresource	es.com		Conditions of				Attached	П		
Date: 0	3/21/2012	ם	hone:	432-212-2399	1					Attached	<u>.</u>		
Date: 03 Attach Addit				734-412-4377		Remediation per OCD Rules &							
,		11 1	- )				BMIT REMED		V	ØT.	4	12/0	
					PRO	POSAL NO	T LATER THAI	N:					

October 4, 2012