

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-016-22218

Release Notification and Corrective Action

nMLB0512230909

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG Operating LLC	Contact	Diane Kuykendall
Address	550 W. Texas Ave., Suite 1300 Midland, TX 79701	Telephone No.	432-683-7443
Facility Name	Keystone #4	Facility Type	Oil Well

Surface Owner	Don Rains	Mineral Owner		Lease No.	301047
---------------	-----------	---------------	--	-----------	--------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	32	20S	28E	1650	North	1980	West	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release	produced oil & water leak	Volume of Release	>5 bbls	Volume Recovered	
Source of Release	Valve at base of Tank leaking	Date and Hour of Occurrence	Prior to 4/13/05	Date and Hour of Discovery	4/13/05 by OCD
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Mike Bratcher contacted us	Date and Hour	4/13/05	<b>RECEIVED</b>	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

APR 18 2005


OCD-ARTESIA

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Leak at tank valve. Vacuum truck pulled free standing fluids. Isolated tank and preparing to fix tank. Highlander was contacted for remediation plan.

Describe Area Affected and Cleanup Action Taken.\*  
Dike was 1/4 full. With fluids. Free standing fluids were pulled off. Preparing to fix tank.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Diane Kuykendall	Approved by District Supervisor: <b>TIM GUM by MB</b>		
Title: Production Analyst	Approval Date: 5/2/05	Expiration Date: N/A	
E-mail Address: dkuykendall@conchoresources.com	Conditions of Approval: Submit Remediation Workplan	Attached <input type="checkbox"/>	
Date: 4/15/05	Phone: 432-685-4372		

\* Attach Additional Sheets If Necessary