


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

15MW/12255-2006

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	192463	Contact	Christopher Jones
Address	1502 W. Commerce Drive, Carlsbad, NM		Telephone No.	(575) 628-4121
Facility Name	Winston Gas Com Btry		Facility Type	Gathering

Surface Owner	BLM	Mineral Owner		Lease No.	NM LC 063246
---------------	-----	---------------	--	-----------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	31	21S	24E					Eddy County, NM

Latitude N 32.441

Longitude W 104.536

NATURE OF RELEASE

Type of Release	Oil and Produced Water	Volume of Release	700 bbls	Volume Recovered	650 bbls
Source of Release	Gasket failure on free water knockout	Date and Hour of Occurrence	08/10/2012 @ 8:00 am	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD; Terry Gregston-BLM		
By Whom?	Chris Jones	Date and Hour	08/14/2012 @ 10:08 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully *

Describe Cause of Problem and Remedial Action Taken.*

A gasket failure on the free water knockout caused 700 bbls of oil and produced water to leak onto the ground. 650 bbls of liquid were recovered via vacuum truck. Remediation will be performed according to a NMOCD and BLM approved remediation plan.

Describe Area Affected and Cleanup Action Taken.*

The area affected is approximately 60' x 150'. 650 bbls of oil and produced water were recovered and additional remediation will be performed according to a NMOCD and BLM approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Christopher Jones		Approved by District Supervisor.	Signed By: <i>Mike Bratcher</i>
Title: HES Specialist		Approval Date: SEP 11 2012	Expiration Date:
E-mail Address: Christopher_Jones@oxy.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date:		Phone: (575) 328-4121	

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

October 11th 2012

2RP-1281