


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

MLB 11255-4842

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Alamo Permian Resources, LLC	Contact	Steven Mastin
Address	415 W. Wall St. Suite 500	Telephone No.	(432) 557-5847
Facility Name	Berry A #33	Facility Type	

Surface Owner	Federal	Mineral Owner	Federal	Lease No.	API No. 30-015-25154
---------------	---------	---------------	---------	-----------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	24	17-S	27-E	1650	South	2040	West	Eddy

Latitude N 32.81684° Longitude W 104.23415°

NATURE OF RELEASE

Type of Release: Water	Volume of Release 25 bbls	Volume Recovered
Source of Release Overflow tank	Date and Hour of Occurrence Aug 30, 2011	Date and Hour of Discovery Aug 30, 2011
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Steven Mastin	
By Whom? Ricky Rodriguez, pumper	Date and Hour Aug 30, 2011	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Electrical malfunction caused an injection pump to be down long enough that the overflow tank ran over

Describe Area Affected and Cleanup Action Taken.*

Tetra Tech inspected site and collected samples to define spills extent. Soil with elevated chloride concentrations was removed and hauled away to Gandy Marley, Inc. Additional areas, at the request of the BLM, were excavated and lined. The Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Carie Stoker</u>	OIL CONSERVATION DIVISION	
Printed Name <u>Carie Stoker</u>	Signed By <u>Mike Benner</u>	
Title <u>Reg Affairs Coord</u>	Approved by District Supervisor:	
E-mail Address: <u>estoker@halmsoil.com</u>	Approval Date: <u>NOV 19 2012</u>	Expiration Date: <u>N/A</u>
Date: <u>7/18/12</u> Phone: (432) 664-7659	Conditions of Approval: <u>W/4</u>	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-891