

RECEIVED
JUL 28 2005
OCCUPANCY
JUL 28 2005

30-015-34037

***** CHART SCANNER WELL TEST DATA *****

COMPANY: MARBOB ENERGY
CLIENT: CHARLIE NUNNLEE
GAUGE NUMBER: 576
WELL NAME: SPANISH DAGGER STATE
WELL NUMBER: #1
TEST NUMBER: 1
LOCATION:
TEST OPERATOR: J GUAJARDO/KELTIC SERVICES
COMMENTS: TOP OF CEMENT AT 1400 FT
DATE OF TEST 7-22-2005

DATE: 07/22/05

GAUGE S/N: 576

REAL TIME	DELTA TIME HRS	TEMPERATURE Deg F	DEPTH FEET	FLOW RATE BBLs/DAY	COMMENTS
10:00:25	0.007	66.73	0.00		
10:05:28	0.091	67.11	100.00		
10:09:04	0.151	64.99	500.00		
10:11:16	0.188	64.99	1000.00		
10:14:10	0.236	64.99	1200.00		
10:16:23	0.273	65.16	1400.00		TOP OF CEMENT
10:18:32	0.309	66.22	1600.00		
10:20:30	0.342	68.10	1800.00		
10:22:22	0.373	69.72	2000.00		
10:25:10	0.420	71.41	2200.00		
10:27:22	0.456	72.60	2400.00		
10:29:04	0.485	73.87	2600.00		
10:30:59	0.516	74.80	2800.00		
10:33:04	0.551	75.99	3000.00		
10:35:51	0.598	77.19	4000.00		
10:39:15	0.654	78.25	6000.00		
10:41:53	0.698	79.23	8000.00		
10:45:02	0.751	80.32	8340.00		TAG TD

COMPANY: MARBOB ENERGY
CLIENT: CHARLIE NUNNLEE
GAUGE NUMBER: 576
WELL NAME: SPANISH DAGGER STATE
WELL NUMBER: #1

TEST NUMBER: 1
LOCATION:
TEST OPERATOR: J GUAJARDO/KELTIC SERVICES
COMMENTS: TOP OF CEMENT AT 1400 FT
DATE OF TEST 7-22-2005

