

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-31403

Release Notification and Corrective Action

nMLB 0525733730

OPERATOR

X ☐ Initial Report ☐ Final Report

Name of Company OXY USA	Contact Rick Kerby
Address 1017 W. Stanolind Rd. Hobbs, NM 88240	Telephone No. (O) 393-2174 C) 631-4972
Facility Name OXY Wacky Pack Fed #1	Facility Type Production Facility

Surface Owner BLM	Mineral Owner	Lease No.
-------------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter E	Section 13	Township 17S	Range 27E	Feet from the 1650	North/South Line North	Feet from the 660	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release Water inside Dike	Volume of Release App 25 bbl	Volume Recovered 0 bbl
Source of Release Battery struck by lightning and exploded	Date and Hour of Occurrence UNK	Date and Hour of Discovery 8-18-05 11:15 PM
Was Immediate Notice Given? Required X <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? Jerry Guye NMOCD	
By Whom? Rick Kerby OXY USA HES Tech	Date and Hour 8-19-05 5:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Lightning struck battery and all three tanks exploding. Oil was contained in steel oil tanks and fiberglass water tank was destroyed and emptied water inside dike. All water stayed in dike.

Describe Area Affected and Cleanup Action Taken.\*

No water was released outside of diked area. Battery will be dismantled and possibly rebuilt.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Rick Kerby	Approved by District Supervisor: <b>TIM GUM</b> by MB <i>Mike Lumsden</i>		
Title: HES Tech	Approval Date: 9/14/05	Expiration Date:	
E-mail Address: rick_kerby@oxy.com	Conditions of Approval: Submit Status Report	Attached <input type="checkbox"/>	
Date: Phone: 631-4972			

\* Attach Additional Sheets If Necessary