

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW 1231134517

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Legacy Reserves Operating, LP 240974 Contact: Berry Johnson
Address: PO Box 10848, Midland, TX 79702-7848 Telephone No.: 432-689-5200
Facility Name: South Red Lake II Unit #28 Facility Type: Injection

Surface Owner Mineral Owner: State API No. 30-015-00683

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	36	17S	27E	965'	South	1650'	West	Eddy

Latitude 32.7896 Longitude 104.2350

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 25 bbls	Volume Recovered: 20 bbls
Source of Release: Injection line leak	Date and Hour of Occurrence: 10/19/12	Date and Hour of Discovery 10/19/12
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED
OCT 29 2012
NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.*

Hole in injection flowline which affected 10' x 10' and also ran down county road gathering on the pavement measuring 25' x 50'. Flowline repaired and vacuum truck picked up 20 bbls of fluid. Dug up affected soil (10-12yds) and put on plastic.

Describe Area Affected and Cleanup Action Taken.*

10' x 10' area at leak site. Fluid picked up and soil dug up. Remediation will be turned over to Talon Environmental.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Berry Johnson</i>	OIL CONSERVATION DIVISION	
Printed Name: Berry Johnson	Approved by Environmental Specialist: <i>Mike Brannon</i>	Signed By: <i>Mike Brannon</i>
Title: Operations Superintendent	Approval Date: NOV 06 2012	Expiration Date:
E-mail Address: bjohnson@legacylvp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/23/2012 Phone: 432-689-5200		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION**

PROPOSAL NOT LATER THAN:

Dec. 6, 2012

2RP-1385