


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

Operator ☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	SRO 102 SWD	Facility Type	SWD
Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-21398

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	16	26S	28E					Eddy

Latitude 32 02.657 Longitude 104 05.431

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	75bbbs	Volume Recovered	0bbbs
Source of Release	4" discharge line	Date and Hour of Occurrence	10/21/2012	Date and Hour of Discovery	10/21/2012
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD		
By Whom?	Michelle Mullins	Date and Hour	10/23/2012 11:17 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Our 4" produced water discharge line corroded and released fluid onto the SRO 102 SWD location. The discharge line has been repaired and returned to service.

Describe Area Affected and Cleanup Action Taken.*

Initially approximately 75bbbs were released onto the pad location at the SRO 102 SWD. We were unable to recover any of the fluid with vacuum trucks. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:			
Printed Name:	Josh Russo	Approved by District Supervisor:	Signed By
Title:	Senior Environmental Coordinator	Approval Date:	NOV 06 2012
E-mail Address:	jrusso@concho.com	Expiration Date:	
Date:	10/25/2012	Phone:	432-212-2399
Conditions of Approval:		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:
Dec. 6, 2012

2RP-1388