


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

**Release Notification and Corrective Action**

nJM W 12311 29593

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <b>260737</b>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Delaware "C" Tank Battery, same well pad as the PLU-153	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-31412
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter G	Section 6	Township 24S	Range 30 E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude **N 32.248735** Longitude **W 103.918797**

**NATURE OF RELEASE**

Type of Release: Produced water	Volume of Release: 650 bbls produced water	Volume Recovered: 0 bbls
Source of Release: 8" suction line to SWD H-pump	Date and Hour of Occurrence: 8/19/12 time approximately 12:00 a.m. <b>9/19/12</b>	Date and Hour of Discovery: <b>8/19/12</b> 2:00 a.m. <b>9/19/12</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Artesia NMOCD emergency #104 and Jim Amos with the BLM	
By Whom? Tony Savoie	Date and Hour: 8/19/12 at 8:52 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A connection going from the charge pumps to the H-pump failed, the pumps were shut down upon discovery and the line was repaired the next morning.

Describe Area Affected and Cleanup Action Taken.\*

The area around the SWD battery, the road and pasture were impacted by the new release, the same areas involved had been impacted by recent releases at the same location. A rig is being scheduled to determine the vertical extent under the containment and all of the impacted areas. The spill will be remediated in accordance to the NMOCD recommended guidelines for spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by Environmental Specialist: Signed By <i>Mike Brandon</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <b>NOV 06 2012</b>	Expiration Date:
E-mail Address: tasavoie@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9/28/12	Phone: 432-556-8730	

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**

**December 6<sup>th</sup> 2012**

**2RP-1382**