

District I
1625 N. Francis Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1231131067

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Devon Energy Production LP 6137	Contact: Daniel Suniga
Address: P.O. Box 250 Artesia, N.M. 88211	Telephone No. 575-390-5850 30-015-33439
Facility Name: Apache 25 # 8	Facility Type: Oil Well # 30-015-27896

Surface Owner	Mineral Owner	Lease No. NMNM-89052
---------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter G	Section 25	Township 22S	Range 30E	Feet from the 1980	North/South Line North	Feet from the 1650	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 520 bbls	Volume Recovered: 520 bbls
Source of Release: water pump malfunction	Date and Hour of Occurrence: 10/13/2012, 4:00 PM	Date and Hour of Discovery 10/14/2012, 8:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Daniel Suniga, Production Foreman	
By Whom? Jerry VanNatta, Lease Operator	Date and Hour: 10/14/2012, 8:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* N/A

RECEIVED

OCT 24 2012

NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.

While on his route the Lease Operator for the Apache 25 # 8 location discovered a water pump had went down causing tanks to run over into containment producing a 520 bbl. water spill with 520 bbls. recovered.

Describe Area Affected and Cleanup Action Taken.*

After discovering the spill at the Apache 25 # 8 location, the Lease Operator called for trucks to clean up the spill, contacted his foreman, and then reset the pump to resume service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Rebecca Raga	OIL CONSERVATION DIVISION	
Printed Name: Rebecca Raga	Approved by District Supervisor:	Signed By: Mike Brandon
Title: Field Tech	Approval NOV 06 2012	Expiration Date:
E-mail Address: rebecca.raga@dm.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/17/2012 Phone: (575) 746-5564		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:
Dec. 6, 2012

2RP-1384