

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW1231137859

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company SM ENERGY COMPANY <i>154903</i>	Contact VICKIE MARTINEZ
Address 3300 N "A" ST BLDG 7-200 MIDLAND, TX 79705	Telephone No. (432)688-1709
Facility Name PARKWAY 35 FEDERAL COM 4H 30-015-3983	Facility Type WELL

Surface Owner BUREAU OF LAND MANAGEMENT	Mineral Owner BUREAU OF LAND MANAGEMENT	API No. NMNM24160&NM67102
---	---	---------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	35	19S	29E	450	SOUTH	330	WEST	EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release PRODUCED WATER	Volume of Release 15 BBLS	Volume Recovered 15 BBLS
Source of Release 3" POLYETHYLENE LINE	Date and Hour of Occurrence 10/19/12 4:00 PM	Date and Hour of Discovery SAME
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? JIM AMOS WITH BLM AND NMOCD VOICEMAIL	
By Whom? BILL HEARNE	Date and Hour 10/19/12 4:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

RECEIVED
OCT 29 2012
NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.*

TALON LPE WSA WORKING ON ACCESS ROAD LOWERING POLYETHYLENE LINES BEFORE PUTTING DOWN CALICHE. LINES WERE VISIBLE BUT ACCIDENTALLY HIT. TWO SPOTTERS WERE ON LOCATION AT TIME OF INCIDENT. ALL STANDING FLUID WAS PICKED UP AND POLYETHYLENE LINE WAS REPAIRED.

Describe Area Affected and Cleanup Action Taken.*

SPILL AREA: 15'X15' = 225 SQ FT

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Vickie Martinez</i>	OIL CONSERVATION DIVISION	
Printed Name: VICKIE MARTINEZ	Approved by Environmental Specialist:	Signed By: <i>Mike Benavidez</i>
Title: ENGINEER TECH II	Approval Date: NOV 06 2012	Expiration Date:
E-mail Address: VMARTINEZ@SM-ENERGY.COM	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/22/2012 Phone: (432)688-1709		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

Dec. 6, 2012

2RP-1386