


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

JMW 1234851101

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Way South State Com #1H	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-37234

**LOCATION OF RELEASE**

Unit Letter A	Section 30	Township 26S	Range 28E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32 01.128 Longitude 104 07.136

**NATURE OF RELEASE**

Type of Release Produced water / Oil	Volume of Release 25bbls pw 5bbls oil	Volume Recovered 15bbls pw 2bbls oil
Source of Release FWKO	Date and Hour of Occurrence 11/28/2012	Date and Hour of Discovery 11/28/2012 11:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-OCD	
By Whom? Michelle Mullins	Date and Hour 12/03/2012 8:59 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A failed gasket at the FWKO inside the Way South State Com #1H facility failed allowing the release of produced fluids into the facility. The failed gasket has been replaced.

Describe Area Affected and Cleanup Action Taken.\*

Initially 30bbls of produced fluid were released from the FWKO and we were able to recover 17bbls with a vacuum truck. The release was contained inside the containment at the Way South State Com #1H facility. All free fluid has been recovered from the spill area. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOC D for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature:	Approved by District Supervisor: Signed By	
Printed Name: Josh Russo	Approval Date: DEC 13 2012	Expiration Date:
Title: Senior Environmental Coordinator	Conditions of Approval:	Attached <input type="checkbox"/>
E-mail Address: jrusso@concho.com		
Date: 12/10/2012 Phone: 432-212-2399		

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules &  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:  
January 13, 2012

2RP-1450