

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW 1235332604
Name of Company: BOPCO, L.P. 260737 OPERATOR ☒ Initial Report ☐ Final Report
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Contact: Tony Savoie
Facility Name: Remuda Basin Battery #1 Well Location Telephone No. 575-887-7329
Facility Type: Exploration and Production
Surface Owner: State of N.M. Mineral Owner: State of N.M. API No. 30-015-03691

LOCATION OF RELEASE

Unit Letter I	Section 24	Township 23S	Range 29E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude: N 32.288041 Longitude: W 103.936333

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: Unknown	Volume Recovered: None
Source of Release: Unknown truck unauthorized release	Date and Hour of Occurrence: Date and hour unknown	Date and Hour of Discovery: 11/26/12 8:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104	
By Whom? Tony Savoie	Date and Hour 11/26/12 at 10:22 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The spill was caused by an un-authorized release on the well pad location.		
Describe Area Affected and Cleanup Action Taken.* Well pad location, drilling reserve pit, and pasture land. No clean has been initiated pending investigation at the site. The affected area in the pasture will be remediated in accordance to the NMOCD guidelines.		

RECEIVED

DEC 17 2012

NMOCD ARTESIA

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Tony Savoie	Approved by Environmental Specialist: Signed By M. L. Brannon	
Printed Name: Tony Savoie	Approval Date: DEC 18 2012	Expiration Date:
Title: Waste Management and Remediation Specialist	Conditions of Approval:	
E-mail Address: tasavoie@basspet.com	Attached <input type="checkbox"/>	
Date: 12/17/12	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:
January 18th, 2013

2RP-1458