<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
811 S. 1^a Street, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

DEC 1 0 2012

RECEIVED

Form C-141 Revised October 10, 2003

Oil Conservation Division

Submit 2 Copies to appropriate trict Office in accordance with Rule 116 on back side of form

1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action												
MMCa	12352	34054	0	PERA	ATOR		☐ Initial Report ☐ Final Report					
Name of Co	OGRID Nu	OGRID Number		Contact					- 			
Yates Petro	leum Cor	oration		25575		Amber Can						
Address 105 S. 4 TH Street						Telephone No. 575-748-1471						
Facility Name Amole AMM Battery NDD (1244) API Number 30-015-27314						Facility Type Battery						
Surface Ow	mer		Mineral (Dwner		Lease No.						
State State							LG-864					
LOCATION OF RELEASE												
Unit Letter M						orth/South Line Feet from the South 660			Vest Line County Vest Eddy			•
Latitude 32.65569 Longitude 103.49575												
NATURE OF RELEASE												
Type of Rele		O:1		Volume of Release			Volume Recovered					
Produced water / Crude Oil Source of Release						20 B/PW; 10 B/O Date and Hour of Occurrence			5B/PW, 5 B/O Date and Hour of Discovery			
Heater Treate Was Immedia		Sitran 9		12/7/2012;	12/7/2012	12/7/2012; AM						
Was minicula	ate ivolice (equired	If YES, To Whom? Mike Bratcher, NMOCD II								
By Whom? Robert Asher				Date and Hour 12/7/2012; PM								
Was a Water				If YES, Volume Impacting the Watercourse.								
If a Watercou	rse was Im		Yes ⊠ he Fully.*		N/A				 			
If a Watercourse was Impacted, Describe Fully.* N/A												
Describe Cause of Problem and Remedial Action Taken.* The ninety in front of the heater treater had a hole in it, spilling oil and water. The well to the facility was shut in, the leak was isolated.												
Describe Area Affected and Cleanup Action Taken.*												
An approximate area of 40' X 25' (inside an unlined/earthern berm). The leak was isolated. All impacted soils will be taken to a NMOCD approved disposal facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial												
analytical results for TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the												
analytical results are above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (95', Section 16, T19S-R25E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger												
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health												
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION												
Signature	mh.	Ca		1/								
			A	Approved by District Supervisor: Signed By Mile Benniere								
Printed Name:	Amber Car	nnon				DEC	1 7 2012					•
Title: Environ	mental Reg	ulatory Agent				Approval Date: 1 7 2012 Expiration Date:					· · · · ·	
E-mail Address: acannon@yatespetroleum.com						Conditions of Approval:						
Date: Monday, December 10, 2012 Phone: 575-748-4111												
Attach Additional Sheets If Necessary Remediation per OCD Rules & 2RP-145 Guidelines, SUBMIT REMEDIATION												1454