Submit One Copy To Apprese OrrigiVED	tate of New M	[evico	· .	Form C-103	
Office <u>District I</u> 16 2013 Energy, M 1625 N. French Dr., Hobbs, NM-88240 6 2013 Energy, M	finerals and Nat	tural Resources		Revised November 3, 2011	
1625 N. French Dr., Hobbs, NM-88240 6 2013 2000, 70			WELL API NO.		
District II 811 S. First St., Artesia, NM 88310D ARTESO/PLICO District III	NSERVATIO	N DIVISION	30-015-25508	oflesse	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	20 South St. Francis Dr.		5. Indicate Type of Lease STATE STATE FEE		
District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505					
SUNDRY NOTICES AND REPO			7. Lease Name of	or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OF DIFFERENT RESERVOIR. USE "APPLICATION FOR PERM			Amoco State A		
PROPOSALS.)			8. Well Number 2		
1. Type of Well: Oil Well Gas Well O 2. Name of Operator	Other		9. OGRID Number		
COG Operating LLC			229137	DEI	
3. Address of Operator			10. Pool name o	r Wildcat	
One Concho Center, 600 W. Illinois Avenue, Midla	nd, TX 79701		Artesia;Queen-G	irayburg-San Andres	
4. Well Location	-	,			
Unit Letter <u>A</u> : <u>443</u> feet from the <u>North</u>		•			
Section <u>34</u> Township <u>17S</u> Range <u>28H</u>		County Eddy			
11. Elevation (<i>R, RKB, RT, GR, etc.)</i> 2' GR	· .		
12. Check Appropriate Box to Indicate Natu	· · · · · · · · · · · · · · · · · · ·		ata		
PERFORM REMEDIAL WORK DUID AND AE					
PULL OR ALTER CASING MULTIPLE CO	— — — — — — — — — — — — — — — — — — — —				
			_		
OTHER: All pits have been remediated in compliance wit	Location is ready for OCD inspection after P&A				
 All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. 					
A steel marker at least 4" in diameter and at least 4" above ground level has been set in concrete. It shows the					
ODEDATOD NAME I FASE NAME WELL NU		MDED OUADTED			
OPERATOR NAME, LEASE NAME, WELL NU LETTER, SECTION, TOWNSHIP, AND RANGE					
STAMPED ON THE MARKER'S SURFACE.					
	,				
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.					
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.					
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with					
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.					
\boxtimes All metal bolts and other materials have been rem	noved. Portable l	bases have been remov	ved. (Poured onsite	e concrete bases do not have	
to be removed.)			`		
All other environmental concerns have been add			A 11 (0. 1 J - 1 1.	1.6	
Pipelines and flow lines have been abandoned in retrieved flow lines and pipelines.	i accordance with	19.15.55.10 NMAC.	All fluids have be	sen removed from non-	
☐ If this is a one-well lease or last remaining well	on lease: all elect	rical service poles and	l lines have been r	emoved from lease and well	
location, except for utility's distribution infrastructur	e.		•		
When all work has been completed, return this form	to the appropriate	District office to sche	dule an inspection	n	
when an work has been completed, return this form $\sum_{n=1}^{\infty} A_{n}$	to the appropriate	District office to send	dule all inspection	1.	
SIGNATURE S: L.	тіті б	Regulatory Analyst		DATE 1/15/12	
		Allalyst		DATE1/15/13 PHONE: _432-221-0467	
TYPE OR PRINT NAME Brian Maiorino	E-MAIL:	_bmaiorino@concho.	com	PHONE: _432-221-0467	
For State Use Only					
APPROVED BY:	TITLE			DATE 1/ 17/200	
		····			

•

Т	T	ГΙ	Æ

_DATE 1/ 17/2013