

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

DEC 27 2012

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit a copy to appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

NTM 1301454433

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating <i>269324</i>	Contact: Jose Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Skelly Unit # 240	Facility Type: Oil producer
Surface Owner: Federal	Mineral Owner: Federal
API No.: 3001529032	

LOCATION OF RELEASE

Unit Letter L	Section 23	Township 17S	Range 31E	Feet from the 2403	North/South Line South	Feet from the 78	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	---------------------	------------------------	----------------

Latitude: 32.8194587309449 Longitude: -103.848663310665

NATURE OF RELEASE

Type of Release: Oil / Produced Water	Volume of Release: 3bbls / .25bbl	Volume Recovered: 0 / 0
Source of Release: Poly line	Date and Hour of Occurrence: 12/19/2012 10:45am	Date and Hour of Discovery: 12/19/2012 11am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher - NM OCD Terry Gregston-BLM	
By Whom? Jose Hernandez	Date and Hour 12/19/2012 2pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: Drove to check SU #253 400' SW of #253 found. Cause. bulldozer ran across the top of Polly line that laid 2' off side of road. Talked to Bird Electric. they had moved DOZER day before. Bird Electric is taking responsibility for clean up, Rene Frasto w/ BIRD ELECTRIC 432.269.9722 ALLEN 432.557.5142		
Describe Area Affected and Cleanup Action Taken.* : 3 barrels of oil on edge of road and in middle of road with a over spray about 30ft in diameter NE. B.S.G weld poly line.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>[Signature]</i>	Approved by District Supervisor:	Signed By: <i>[Signature]</i>
Printed Name: Jose Hernandez	Approval Date: JAN 14 2013	Expiration Date:
Title: Production Foreman	Conditions of Approval:	Attached <input type="checkbox"/>
E-mail Address: jhernandez@linenergy.com		
Date: 12/27/2012 Phone: 575-942-9492		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:
February 14th 2013**

2RP-1489