


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

NTM 1301556273

Name of Company Oxy Permian Ltd. <i>192463</i>		Contact Christopher Jones
Address 1502 W. Commerce Dr., Carlsbad, NM		Telephone No. (575) 628-4121
Facility Name Jones Canyon 4 Federal #4		Facility Type
Surface Owner	Mineral Owner	Lease No. API#30-015-30487

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	4	22S	24E					Eddy County, NM

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 500 bbls	Volume Recovered 50 bbls
Source of Release Failure in 2" steel production line	Date and Hour of Occurrence 12/13/2012	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher- OCD, James Amos-BLM, Terry Gregston-BLM	
By Whom? Christopher Jones	Date and Hour 12/13/2012 @ 11:20am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Failure in a 2" steel production line caused 500 bbls of produced water to leak onto the ground. 50 bbls of produced water were recovered via vacuum truck.

Describe Area Affected and Cleanup Action Taken.*

Failure in a 2" steel production line caused 500 bbls of produced water to leak onto the ground. 50 bbls of produced water were recovered via vacuum truck. Remediation will be performed in accordance with an OCD-approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCN rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCN marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCN acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Christopher Jones		Approved by District Supervisor:	
Title: HES Specialist		Approval Date: JAN 15 2013	Signed By:
E-mail Address: Christopher.Jones@oxy.com		Expiration Date:	
Date: 1-3-13 Phone: (575) 628-4121		Conditions of Approval:	
		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: February 15, 2013

2RP-1494