

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

JMW 1301651993

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: EOG Resources, Inc. 7377	Contact: James Fischer
Address: 4000 N. Big Spring Ste 500 Midland, TX 79705	Telephone No. 432-686-3747
Facility Name: Ross Gulch 8 Fed Com 1H	Facility Type: Oil and Gas tank battery

Surface Owner: BLM	Mineral Owner: BLM	API No. 30-015-39171-00-X1
--------------------	--------------------	----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	8	26 South	31 East	330'	South	1540'	West	Eddy

Latitude 32.0636885 Longitude 103.8035110

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 10 BBLS	Volume Recovered: 0 BBLS
Source of Release: Tank Battery	Date and Hour of Occurrence: 12/05/2012 - 0300	Date and Hour of Discovery: 12/06/2012 - 0620
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey R. Leking	
By Whom? James Fischer	Date and Hour: 12/12/2012 - 10:30	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED
DEC 31 2012
NMOCD ARTESIA



Describe Cause of Problem and Remedial Action Taken.*

Lost pressure to separator dump and liquid went through the flare, spraying the pasture west of location. Dump valve will be adjusted.

Describe Area Affected and Cleanup Action Taken.*

Oil sprayed an area in pasture covering approx. 100 yards x 150 yards. Spot mopped the most impacted area with absorbent pads. Bio-remediated in place the entire affected area with approx. 1,500 gallons of 4% Microblaze/Water mixture. This method was approved by BLM and soil samples will be taken to insure proper levels of TPH are reached.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: James Fischer	Approved by Environmental Specialist: Signed By 	
Title: Environmental Manager	Approval Date: JAN 16 2013	Expiration Date:
E-mail Address: James_Fischer@eogresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/12/2012 Phone: 432-686-3747	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: February 16, 2013	

* Attach Additional Sheets If Necessary

2RP-1496