


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Submit to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW 1300342111

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company APACHE CORPORATION 873	Contact NATALIE GLADDEN	
Address PO BOX 1849 EUNICE NM 88231	Telephone No. 575-390-4186	
Facility Name WASHINGTON 33 ST #60	Facility Type PRODUCING WELL	
Surface Owner UNKNOWN	Mineral Owner STATE	API No. 30-015-40116

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	33	17S	28E	855'	FSL	2375'	FEL	EDDY

Latitude

Longitude

NATURE OF RELEASE

Type of Release Brine Water	Volume of Release 15	Volume Recovered 2
Source of Release Valve	Date and Hour of Occurrence 09/03/12	Date and Hour of Discovery 09/03/12
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Natalie	Date and Hour 09/04/12 9:07am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Valve on the transfer line malfunctioned during the cement job and the Q-Max employee could not transfer the fluid from the pit and the pit ran over. The standing fluid was recovered.

Describe Area Affected and Cleanup Action Taken.*

Once the well has been completed and the well is producing, then the remediation will begin, which will be in late December or early January. All NM State Guidelines will be followed to closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	Approved by Environmental Specialist	Signed By
Title: Sr. Environmental Tech	Approval Date: JAN 03 2013	Expiration Date:
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 09/04/12 Phone: 575-390-4186		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: February 3rd 2013**

2RP-1476