Submit One Copy To Appropriate District CEIVED	T ate of New Mexico	Form C-103	
Office Energy, M 1625 N. French Dr., Hobbs, NM 88240 JAN 2 8 ZUIJ District II	inerals and Natural Resources	Revised November 3, 2011	
1625 N. French Dr., Hobbs, NM 88240 JAN 2 8 2013 District II		WELL API NO. 30-015-01569	
811 S. First St., Artesia, NM 8820 ANAOCD ABTES	SERVATION DIVISION	5. Indicate Type of Lease	
1000 Bio Brogge Pd Agtes NM 97410	boutin bt. I fundis D1.	STATE STATE	
District IV 1220 S. St. Francis Dr., Santa Fe, NM	anta Fe, NM 87505	6. State Oil & Gas Lease No.	
87505			
SUNDRY NOTICES AND REPO (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DIFFERENT RESERVOIR. USE "APPLICATION FOR PERM PROPOSALS.)	TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name N.G. Phillips State	
	her	8. Well Number 1	
2. Name of Operator		9. OGRID Number	
COG Operating LLC 3. Address of Operator	·	229137 10. Pool name or Wildcat	
One Concho Center, 600 W. Illinois Avenue, Midlar	d, TX 79701	East Empire; Yates-7R-QN-GRBG	
4. Well Location		1	
Unit Letter <u>G</u> : <u>1650</u> feet from the <u>North</u>	line and 2310 feet from the East line		
Section <u>27</u> Township <u>17S</u> Range <u>28E</u> NMPM <u>County Eddy</u>			
11. Elevation (Show whether DR, RKB, RT, GR, etc. 3618' GR		
12. Check Appropriate Box to Indicate Natu		Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON CHANGE PLAN			
PULL OR ALTER CASING 🛛 MULTIPLE CO		Т ЈОВ 🗌	
OTHER:	∏ ⊠ Location is r	eady for OCD inspection after P&A	
\boxtimes All pits have been remediated in compliance with			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT			
LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY			
STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and			
other production equipment.			
 Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with 			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.)			
All other environmental concerns have been addressed as per OCD rules.			
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.			
If this is a one-well lease or last remaining well o	n lease: all electrical service poles ar	d lines have been removed from lease and well	
location, except for utility's distribution infrastructure			
When all work has been completed, return this form to	the appropriate District office to scl	nedule an inspection.	
SIGNATURE S:	TITLE Regulatory Analyst	DATE1/25/13	
		1	
TYPE OR PRINT NAME Brian Maiorino	E-MAIL: _bmaiorino@conche	D.com PHONE: _432-221-0467	
APPROVED BY: A http:// TITLE DATE 1/29/201			

DATE / /	29	2013
	1	_